

## DRAWINGS

## DRAWINGS




Fig. A

Symbols ♦▲■ corresponds to measured data. All other symbols corresponds to different model fitting.

## DRAWINGS




Fig. 1




Fig. 2

## DRAWINGS




Fig. 3





Fig. 4

## DRAWINGS


110

**Fig. 5**



120

**Fig. 6**



## DRAWINGS

Etching




Fig. 7




Fig. 8

## DRAWINGS




Fig. 9




Fig. 10

## DRAWINGS




Fig. 11




Fig. 12